



HENIXIO AVIATION

RM I 5/F PH 4, GOLDEN DRAGON IND CTR, 182
 TAI LIN PAI RD, KWAI CHUNG, HONG KONG
 www.HenixioAviation.com
 Info@HenixioAviation.com
 +85281700369

PURCHASE ORDER

Order No. PO-2274
 Date: 2024-08-01

Vendor:

AMP Aero Services, LLC
 11900 SW 128th St. Suite 100 Miami, FL 33186.
 USA
 Rohit Suyal
 +91-954-053-8789

Ship to:

RM I 5/F BLK 4 GOLDEN DRAGON IND CTR
 182 TAI LIN PAI RD KWAI CHUNG, HONG KONG
 ATT: Ms. Yan phone: +85281700369
 Vendor Ref.: TOP-40

#	Part Number / Description	Cond	Qty	Unit Price	Total Price
1	822504 / BLADE TURB ROTOR, 4STG Cert Source: FAA/EASA DUAL REL Tag Date: FRESH TAG Lead Time: 7 DAYS	SV	58	\$1,150,00	\$66,700.00
2	798403 / BLADE TURB ROTOR, 3STG Cert Source: FAA/EASA DUAL REL Tag Date: FRESH TAG Lead Time: 7 DAYS	SV	88	\$1,050.00	\$92,400.00

Subtotal:	\$159,100.00
Freight Cost:	\$0.00
Bank Fee:	\$0.00
Total:	\$159,100.00

For Final Decision
 Please provide Form One /Form 8130 (or MFG certs) of these parts to us.
 This P/O is valid based on your delivery time which is in your P/I.
 If Henixio aviation did not receive the goods during this period has right to cancel the P/O.

NOTE:
 1-Please send the shipment under your account number. So please calculate the freight cost and add it to your invoice.
 2-Don't forget to mention vendor reference at the end of the ship to address in all of the shipping documents. (It's very important to us)
 3-We do the payment in wire transfer, so please add the wire transfer fee to the invoice.