



**General Airframe Support**  
 3 W CHALLENGER ST  
 BUILDING 732  
 sales@genairsupport.com  
 ROSWELL, NM 88203  
 USA

**Acknowledgement**

**SO #: 8419**  
 Date Printed: 5/11/2023  
 Time: 7:34:40 AM  
 # of Items: 3  
 Page: 1 of 1  
 Prepared By: Adriana Vasquez

**To:**  
**HENIXIO AVIATION**  
 Room 218-9, 2/Floor, Block B  
 Proficient Industrial Centre  
 +85281700810  
 Kowloon 71027  
 CHINA  
 ATTN: Sabrina Tahirah

**Ship To:**  
 RM I 5/F PH 4 GOLDEN DRAGON IND CTR  
 182 TAI LIN PAI RD KWAI CHUNG  
 ATT: Ms. Yan phone: +85281700369  
 Vendor Ref.: TOP-40  
 HONG KONG  
 CHINA

Date Open: 5/11/2023      Ship Via: TBD      Customer PO#: PO-1671  
 Customer #: HENAV      Ship Via Acc:      Buyer: Markel Traffon

*Thank you for your order!*


Item	Part Number/Description	Delivery	To Ship	BackOrd	CD	List Price	Disc%	Unit Price	Total Amt
1	2-7680-1 FUSE		0	1	OH	4,550	0.00	4,550EA	4,550
2	INTERNATIONAL SHIPPING FEE		1	0		75	0.00	75	75
3	INTERNATIONAL SHIPPING FEE		1	0		40	0.00	40	40
	WIRE FEE WIRE FEE								
	YOUR QUOTED TARGET SHIP DATE IS 06/07/2023 OR SOONER. WE WILL NEED TO RECEIVE PAYMENT BEFORE PART IS RELEASED TO SHIP FROM SHOP. PLEASE SIGN AND RETURN BEFORE I CAN SEND OVER THE WORK ORDER. THANK YOU.								
	<i>Sabrina Tahirah</i> CLIENT SIGNATURE								
	WIRE INSTRUCTIONS/ ACH Wells Fargo Bank, N.A. 1755 W. Valencia Road Tucson, AZ 85746 Attn. Christina Ruiz Christina.g.ruiz@wellsfargo.com ABA: 121000248 Acct.# 3270666591 Swift code: WFBUS6S ACH Routing# 122105278								



ANY SV OR OH UNIT WITH AN AIRWORTHY CERTIFICATE OLDER THAN TWO YEARS WILL BE CONSIDERED AS AN AS-IS WHERE-IS TRANSACTION AND WILL NOT BE CONSIDERED FOR A RMA.  
 RMA AND WARRANTY WILL BE NULL AND VOID IF TAMPER STICKER IS DAMAGED OR BROKEN AND RETURN WILL BE DENIED.

**\*\*LEAD TIME IS QUOTED IN WORKING BUSINESS DAYS\*\***  
 Early cancellation: No Purchase Order may be cancelled without prior written approval from General Airframe Support. If a cancellation request is accepted in writing there will be a 50%, of purchase order price, cancellation fee invoiced.  
 \*\*No returns accepted without proper authorization, a 50% restock fee may apply. GENAIR is not responsible for hole alignment.

<b>Item Total:</b>	4,665
<b>Discount:</b>	
<b>SubTotal:</b>	4,665
<b>Misc Charge:</b>	
<b>Freight:</b>	
<b>Total:</b>	<b>4,665</b>
Payable in USD	

**Authorized Signature:**  
  
 sig