





1. Approving Competent Authority/Country CAA/United Kingdom		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1			3. Form Tracking Number ARC38248	
4. Organisation Name and Address  KEARSLEY AIRWAYS LTD		Kearsley Airways Limited Romeera House Stansted Airport Stansted Essex CM24 1QL United Kingdom		Tel: +44 (0) 1279 871000 Fax: +44 (0) 1279 871187 Email: info@kalair.co.uk Web: www.kalair.co.uk		5. Work Order/Contract/Invoice RO10494/W239812
6. Item 1	7. Description Fan Assembly	8. Part No. D103549	9. Qty. 1	10. Serial No. 483203	11. Status/Work Repaired	
12. Remarks Repaired I.A.W. Airscrew CMM 21-22-17 Rev 2 Dated December 1994. Our Workshop Inspection Report W239812 refers. "Released For Balance Of Life, Hours/Landings Consumed As Per Customers Records"				Return to Service in accordance with FAR 43.9. Certificate No: LKSY 813K Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Title 14, Code of Federal Aviation Regulations, part 43 and in respect to that work, the items are approved for return to service. Pertinent details of the repair are on file at this repair station under order: No: RO10494/W239812 Sign:  Date: <u>19/11/15</u>		
13a. Certifies that the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in condition for safe operation <input type="checkbox"/> Non-approved design data specified in block 12		14a. <input checked="" type="checkbox"/> Part-145.A.50 Release to Service <input checked="" type="checkbox"/> Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.				
13b. Authorised Signature		13c. Approval/Authorisation Number		14b. Authorised Signature  		14c. Certificate/Approval Ref. No. UK.145.00082
13d. Name		13e. Date (dd mmm yyyy)		14d. Name R.Todd		14e. Date (dd mmm yyyy) 19 Nov 2015
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						



KEARSLEY AIRWAYS LTD



Kearsley Airways Limited
 Romeera House
 Stansted Airport
 Stansted
 Essex
 CM24 1QL
 United Kingdom
 Tel: +44 (0) 1279 871000

EASA Maintenance Org.: UK.145.00082

FAA Repair Station: LKSY 813 K

Workshop Report

No: **IR39437**

Issue: **01**

Date: **22-Oct-15**

XS Aviation Limited
 Unit 8 Sumpters Way
 Brook Side Centre
 Temple Farm Industrial Estate
 Southend-On-Sea
 Essex
 SS2 5RR
 United Kingdom

Attn: Ken Tracy

Tel: +44 (0)1702 464146 Fax: +44 (0)1702 464343

E-Mail: ken.tracy@xsaviation.co.uk

Your Ref: RO10494	Our Ref No: W239812	Test Required: N/A	
Part No: D103549	Description: Fan Assembly	TSN: N/A	CSN: N/A
Serial No: 483203	Workscope: Repair	TSO: N/A	CSO: N/A
Removed From:	Serial No:	Reg No:	Position:

Inspection Findings:

Disassembled for inspection.
 Washers rusty.
 Requires bearings, washer and terminal nuts.
 To be assembled, tested and inspected.
 law Airscrew Howden, 21-22-17.

Signed: _____ Name: _____ Date: ___/___/___

For and on the behalf of Kearsley Airways Limited

Kearsley Airways Limited
 Romeera House, Stansted Airport, Stansted, Essex, CM24 1QL.